




Base from City of Los Angeles, 1:1200, Topographic Map No. M-611, Sheets 78 and 79, 1970.
Most fractures shown here are simplified from Map by
S. Hecker, D.J. Poni, C.D. Garvin, T.J. Powers, T.E. Fumal, J.C. Hamilton
R.V. Sharp, M.J. Rymer, C.S. Prentice and F.R. Cinti
U.S. Geological Survey Open File Report 96-52.
Some added by Kenneth M. Cruikshank

This map is preliminary and has not been reviewed for conformity with U.S. Geological Survey editorial standards or with the North American Stratigraphic Code. Any use of trade, product, or firm names does not imply endorsement by the U.S. Government.



Fractures in Ground and Damage to Houses in Granada Hills Area of Northridge during by 17 January 1994 Northridge, California, Earthquake Sequence

Compiled by Nils A. Johnson